



Figure 4.15 Slumping and cracking of soil near a steep slope adjacent to the highway at Puerto el Gato.



Figure 4.16 Lateral extension cracks in soil, Acatlán de Osorio.