



Figure 4.9 Demolished URM structure in Acatlán de Osorio.



Figure 4.10 Damaged modern reinforced concrete structure in Acatlán de Osorio.